Decontamination of Containment Boom



Jon Boats & Containment Boom to be Decontaminated



Absorbent Material Removed from Bayou Lafourche



Containment Boom and Absorbent Boom Deployed in the Drainage Canal East of the Release Location



Central Crude, Inc.
Valentine Facility
Incident Date: February 22, 2007
Lafourche Parish, Louisiana
March 6, 2007

Drainage Canal



Drainage Canal



Residual Crude Oil Noted on the Northwest Corner of the Drainage Canal



Decontamination of Containment Boom




Central Crude, Inc.
Valentine Facility
Incident Date: February 22, 2007
Lafourche Parish, Louisiana
March 6, 2007

Delivery of Roll Off Boxes



South Embankment of Bayou Lafourche with Absorbent Boom Removed



Central Crude, Inc.
Valentine Facility
Incident Date: February 22, 2007
Lafourche Parish, Louisiana
March 6, 2007

Absorbent Boom Removal: North Embankment of Bayou Lafourche



South Embankment of Bayou Lafourche with Absorbent Boom Removed



Staging Area: Motor Vessel Kylie Williams Traveling West to East



Tug Boat Creole Star pushing the Motor Vessel Kylie Williams

